

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentee: Ralph Cowie

Patent No: 7,055,353 B2

Serial No. 10/710,687

Issued: June 6, 2006

RECEIVED
CENTRAL FAX CENTER

OCT 04 2006

For: PROGRESSIVE STAMPING DIE

Attorney Docket: RAL 0101 PA

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate

OCT 06 2006

of Correction

Certificate of Correction
Commissioner for Patents
P. O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:


Patentee hereby requests under the provisions of 35 U.S.C. Sections 254 and 255 and 37 CFR Sections 1.323 and 1.322(a) for a certificate to correct the errors set forth on the enclosed Certificate of Correction form. Patent Office error is found in Column 6, line 54, and Patentee's errors are those listed in Column 8, lines 3 and 44, and Column 9, line 7.

Please charge required fees or credit any overpayment to deposit account 50-0476.

If said request is granted, Patentee requests the file be forwarded to Certificates of Correction Branch, for issuance of a Certificate of Correction.

Respectfully submitted,

ARTZ & ARTZ, PC



John A. Artz, Reg. No. 25,824

Attorney for Patentee

28333 Telegraph Road, Ste. 250

Southfield, MI 48334

(248) 223-9500

Date:

10/5/06

OCT 11 2006

PTO/SB/44 (04-05)

Approved for use through 04/30/2007. OMB 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 7,055,353 B2

APPLICATION NO.: 10/710,687

ISSUE DATE : June 6, 2006

INVENTOR(S) : Ralph Cowie

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 53, should read as follows:

-- of said coin punch members; and --

Column 8, line 3, should read as follows:

-- collection chute in said second die member at least in part --

Column 8, line 44, should read as follows:

-- collection chute in said second die member at least in part --

Column 9, line 7, should read as follows:

-- axial alignment with said pierce punch member and a product --

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Artz & Artz, PC
28333 Telegraph Road, Suite 250
Southfield, MI 48034

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

OCT 11 2006